Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.

Reset to normal operation (current radiation in µSv/h). average radiation level on last 24 hours ( ).

Pulse count. set count time in seconds with , in minutes, in hours, again to start measure. ( ) flash during measure. Display count.

Pulse rate. ( ) flashes during measure. Display average pulse/second.

Set time and date. set hours with , again set minutes, again sets seconds ( ), and to set date ( ).

Show log. Change interval with and . sets alert level with .

Battery level (Min. 2.7 V). and start/stop ticker ( ).

PC data transfert mode.

Max 3.4 mSv / year or 0.4 µSv / hour. Normal 0.1 ~ 0.2 µSv / hour.
Sensitivity α+β+γ 4 MeV, β+γ 0.2 MeV, γ 0.02 MeV.
Capacity: 7d⇨1 years, 1d⇨2 years, 1h⇨4 weeks, 10 min⇨4 days, 1 min⇨10 hours.